Service Bulletin: RAM Dually TPMS






RAM 3500 DRW with Alloys

Auto Relearn

	2014-2018	2019-2020
Outer Sensor	6829 ¹	6846 ¹
Inner Sensor	6825	6854
Outer Valve	VS-35	VS-35
Inner Valve	VS-241 ²	VS-241 ²



²OE is a rubber VS-65, but Dill recommends a clamp-in VS-241 for easier access.




RAM 3500 DRW with Steels

Auto Relearn

2014-2018

	2014-2010	2010-2020	
Outer Sensor	6815 ¹	6896 ¹	
Inner Sensor	6825	6854	
Outer Valve	VS-65	VS-65 —	
Inner Valve	VS-241 ²	VS-241 ²	

¹Also covered by Dill 5001.





2019-2020

²OE is a rubber VS-65, but Dill recommends a clamp-in VS-241 for easier access.